



Invisible Oil Care is a water-based care product for the maintenance of surfaces that have been treated with WOCA Invisible Oil. This care product refreshes the oiled surface and increases the oil's ability to resist stains and wear. Invisible Oil Care is part of a high quality water-based oiling system and should therefore be used together with WOCA Invisible Oil Primer and Invisible Oil.

- **Cares for and maintains floors that have been treated with Invisible Oil Primer and Invisible Oil**
- **Resistant to liquids such as water, coffee, tea and red wine**
- **Gives the wood a beautiful, breathable soft feel surface**
- **IBR-certified**



AppArea

For care and maintenance of wooden surfaces that have been treated with Invisible Oil Primer and Invisible Oil. The Invisible system has been developed for use with light wood varieties, where a high oiling quality and newly-sanded, untreated appearance are required. The range gives the floor a surface that is both comfortable to walk on and soft to the touch. The floor is also left with a soft, water-resistant surface that is easy to clean and maintain.

Work_Descrip_Label

Preparation_Label It is important that the product, the room and the floor are at a temperature between 59°F and 86°C and that air humidity is approx. 50 %. Wood humidity must not exceed 12%. Make sure that the room is well-ventilated for optimal evaporation and drying time. Clean the surface using WOCA Intensive Wood Cleaner and leave until completely dry.

Always remember to test on a less visible spot to check the compatibility of the surface with the product.

Treatment Thoroughly shake the container, both before and during use. Apply Invisible Oil Care in a thin and even coat, using the WOCA Oil applicator or a wool pad and pad holder. Work in small areas of no more than 215 sq. ft. at a time. Carefully polish the area with a white pad. Use a buffing machine for larger surfaces. Continue polishing until the wood is completely saturated and the surface has a uniform appearance. Remove excess oil care with dry, lint-free cotton cloths or pads attached to the buffing machine until the surface no longer appears wet. The surface can be used with caution after 6-12 hours and is fully hardened after 5 days at room temperature.

NoteTxt Do not expose the floor to water or other liquids for the first 5 days, while Invisible Oil Care is hardening. For optimal cleaning, we recommend WOCA Natural Soap Extra White, which cares for and maintains the surface.

DryingTime

DryingTime Approx. 6-12 hours at 68°F

FullyHard 5 days at 68°F



Techdata_label

| | |
|---------------|---|
| Density | 1.00-1.10 g/ml |
| SolidContent | 12 % |
| ShelfLife | 36M |
| AppTemp | +15-30°C |
| Viscosity | Approx. 25 |
| Consumption | 323-430 SF/L, depending on wood type and surface |
| Colours | Neutral |
| CleaningTools | Use warm water |
| Storage | + 50-77°F. Store carefully. Keep out of reach of children. Must not be exposed to heat (e.g. sunlight). Store frost-free. |
| VOC Max | This product contains max. 10 g VOC/L. Permitted value is 500 g VOC/l (cat.A/i). |
| AvailPotSizes | 1 L |

MaintenanceProd

| | |
|-----------------|---|
| WeeklyCleanProd | Natural Soap White, #511110 |
| MaintenanceHdn | Invisible Oil Care, #525510 |
| RelatedProducts | Invisible Oil Primer, #526025 Invisible Oil, #525010/525025 Intensive Wood Cleaner, #551525 |

Contact_Label

WOCA Denmark A/S
Tvæervej 6
DK - 6640 Lunderskov
T +45 9958 5600
info@wocadenmark.com
wocadenmark.com

Disclaimer_Long